## General Environmental Incident Summary

Incident: 2169 Date/Time Notice: 1/10/2014 1530 DEM Incident No:

Responsible Party: ONEOK Rockies Midstream

Date Incident: 1/3/2014 Time Incident: 1700 Duration: 1 minutes

County: McKenzie Twp: 151 Rng: 103 Sec: 35 Qtr: SE

Lat: 47.85019 Long: -103.17990 Method: Interpolation from map

Location Description: Garden Creek Compressor Station

3007 121 Avenue NW Watford City, ND 58854

Submitted By: Jason Lyons Affiliation:

Address: 2700 Lincoln Ave.

City: Sidney State: MT Zip: 59270

Received By:

Contact Person: Jason Lyons

2700 Lincoln Ave Sidney, MT 59270

Distance Nearest Occupied Building: 1 Miles

Type of Incident: Tank Overflow

Description of Released Contaminant: Natural Gas Liquids (Condensate)

Volume Spilled: 84.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Tank overlfow due to trapped pig.

Risk Evaluation:

No impact to human health.

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 05 - air and soil

Potential Environmental Impacts:

No impact to surface water or groundwater.

Action Taken or Planned:

Estimated 2 barrels released inside secondary containment structure. No offsite impacts.

Wastes Disposal Location: Waste recovered via vac truck.

Agencies Involved: Local Emergency Manager

Friday, January 27, 2017 Page 1 of 2

## **Updates**

Date: 1/13/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Volume:** 

Notes:

Reported release into secondary containment structure. Followup is necessary to confirm containment and cleanup.

Date: 2/11/2014 Status: Inspection Author: Martin, Russell

**Updated Volume:** 

## Notes:

2/11/2014 at 12:59, on location. Site is adjacent to Garden Creek Plant. Stain visible within secondary containment. Small (~2x5 foot) spot of stained gravel outside secondary containment but within facility fence. No visible staining outside of facility fence. Will discuss cleanup details with company rep tomorrow.

Date: 8/5/2014 Status: Inspection Author: Martin, Russell

**Updated Volume:** 

## Notes:

Followed up during inspection of more recent spill at same location. See oilfield incident ID 20140714123300 for report.

Friday, January 27, 2017 Page 2 of 2